

The Challenge

This was a fairly new property with extensive water intrusion problems. Pillar Construction addressed the issues related to exterior walls and windows. Climate and site conditions were difficult.

The Solution

The building was in use and occupied. The scope of the work required coordination with other contractors to limit the extent of our work to the exterior face of the walls. New windows and new flashing were added per most current construction industry stucco details. The walls were recoated for a clean and new look.

Our extensive experience is the added value that your restoration project demands

Construction Team:

Restoration Contractor
Pillar Construction Inc Houston TX
www.pillarconstruction.com
Owner
Paramount Homes
Restoration materials and EIFS system components
www.dryvit.com

