

The Challenge

The job was to make the face of the building harmonize with the recently finished office, residential and hotel buildings that completed the development.

New color scheme and repairs to the exterior wall were needed to bring the building facade to the level that the adjacent new construction demanded.

The Solution

While open for business, the high rise exterior wall areas were repaired and recoated. The round low rise portion of the building was in need of new EIFS to reduce the imperfections on the cast in place exterior walls. Critical light made more evident the concrete wall imperfections. A layer of EIFS provided a light weight efficient solution while giving a perfect canvas to promote the building logo and make the end wall a perfect accent element. The landscape and site conditions along with the restrictions from the hotel management such as not covering views of guest rooms, required us to use boom lifts. Pillar understands the needs of the customers and makes the necessary accommodations to get the job done even under very special conditions

■ Our extensive experience is the added value that your restoration project demands