

Vistas Condominiums Restoration

Oakton, VA

The Challenge

The project was a garden style low rise group of buildings with brick, EIFS and Stucco exterior. The Engineer proposed new EIFS skin over Stucco areas, repair and recoating of EIFS areas, window replacement and renovation of exterior features for a complete new skin.

The Solution

Pillar phased the demolition and window replacement to accommodate owners needs. New EIFS over Stucco areas and EIFS skin recoat were completed once the new windows were in place. The building management coordinated the access to individual units for window replacement. The landscape and building configuration presented additional challenges for accessing the wall areas and to complete the project.

Our extensive experience is the added value that your restoration project demands

Construction Team:

Restoration Contractor
Pillar Construction Inc Alexandria VA
www.pillarconstruction.com
Skin Consultant
RCLA
Restoration materials and EIFS system components
Sto Corp www.stocorp.com

Alexandria VA - Orlando FL - Houston TX - Austin TX - Salem NH

We offer a complete package of services ranging from inspections, material selection, installation and maintenance.