

The Challenge

Classical Victorian style ocean front property with water intrusion and skin damages. Pillar Construction was hired to work on the complete replacement of the building skin. New EIFS with proper window details was installed. Pillar had to meticulously rework the facade details to maintain the original look of the building.



The Solution

The building was fully functioning and occupied. Tenants and owners went through the construction process totally informed of the steps and process. Pillar collaborated with the HOA and board to illustrate the extent of the work and improve communication with building occupants. Pillar brought past renovation experience to the design process reducing the waiting time for special site condition detailing.



Our extensive experience is the added value that your restoration project demands

Construction Team:

Restoration Contractor
Pillar Construction Inc Alexandria VA
www.pillarconstruction.com
Restoration materials and EIFS system
PAREX www.parexusa.com

Alexandria VA - Orlando FL - Houston TX - Austin TX - Salem NH

We offer a complete package of services ranging from inspections, material selection, installation and maintenance.