

Windows Condominiums Restoration Princeton, NJ

The Challenge

Recently completed building that presented water infiltration at windows and penetrations. Fully occupied building that needed facade repairs while minimizing disruption to residents' everyday living.

The Solution

The project included: EIFS repairs and exterior sheeting replacement at areas around the windows, update of EIFS termination details, added flashing and new color scheme.

Our extensive experience is the added value that your restoration project demands

Construction Team:

Restoration Contractor
Suffok Construction Boston, MA
Pillar Construction Inc Alexandria VA
www.pillarconstruction.com
Restoration materials and EIFS system components
Sto Corp www.stocorp.com

Alexandria VA - Orlando FL - Houston TX - Austin TX - Salem NH
We offer a complete package of services ranging from inspections, material selection, installation and maintenance.