

The Challenge

Complete demolition and reinstallation of hard coat stucco exterior cladding on a luxurious beach resort. Pillar's seasoned superintendents made this project look like an easy task. Window installation, flashing and waterproofing detailing for a full new hard coat stucco skin were part of the full scope of work.

The Solution

Pillar construction team implemented a demolition program to meet the consultant and owner's time constraints.

Proactive approach and past experience of Pillar field personnel anticipated detail conflicts reducing the time for solving unanticipated field conditions. Total collaboration with consultants provided added value to the project.

Our extensive experience is the added value that your restoration project demands

Construction Team:

Restoration Contractor
Pillar Construction Inc Alexandria VA
www.pillarconstruction.com
Consultant
Tadger Cohen Edelson Associates Engineering
Restoration materials and stucco system components
Sto Corp www.stocorp.com

Alexandria VA - Orlando FL - Houston TX - Austin TX - Salem NH

We offer a complete package of services ranging from inspections, material selection, installation and maintenance.